
| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page <u>1</u> of <u>3</u> | |
|---|---------------------------|---|
| Sewershed: JONES FALLS SEWERSHED | Company: Savin Engineers | Date: 7/30/08 |
| Test to be Performed: | Ground Condition: | Supervisor: RT |
| Smoke: _X Dyed Water: | Dry:X Damp: Wet: | |
| Manhole ID: S35EE 036 | Test ID: 0994-685 | Notifications Made: x (Residents, Fire, 311) |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM | | | | | | | Page 2 of 3 | | |
|---|-------------------|--------------------------|----------|-------------|--|-------------------|-------------|----------|---------|
| Sewershed: Jones Falls | | | Compan | ıy: Savin I | Engineers | Date: 7/30/08 | | | |
| Test to be Performed: | | Ground Condition: | | | | Supervisor: RT | | | |
| Smoke | e: X Dye | d Water: | _ | Dry: X | Dam | p: We | | | |
| Manhole ID: S35EE 036 | | Test ID: | 0994-685 | ; | Notifications Made:X (Residents, Fire, 311) | | | | |
| Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers) | | | | | | | | | |
| Defect | | | | Source | | | Drainage | , | Photo |
| No. | | Address | | Туре | Location | Sector | Area | Severity | Number |
| | 1224 Calvert St | treet | | 05 | 01 | 02 | 500 | 03 | OB01-01 |
| | 1226 Calvert St | | | 03 | 08 | 02 | 0 | 03 | OB02-01 |
| | 1220 0411011 0 | | | | | V2 | | | 0202 01 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | OBSERV | ATION | CODES | | | |
| | Source Type | Location | Sector | Severity | 711011 | Source Type | Location | | |
| 01 | Main Sewer | Paved Concrete | Public | No Smoke | 10 | MH Frame Seal | Non-Paved | | |
| | Service Line | Paved Asphalt | Private | Trace | | Storm Drain | Field/Woods | | |
| | Cleanout | Paved Other | . IIVato | Moderate | | Catch Basin/Inlet | + | | |
| | Downspout | Driveway | | Major | | Storm Manhole | Golf Course | | |
| | Area Drain | Sidewalk | | iviajui | | Storm Ditch | Other | | |
| | Driveway Drain | Curb | | | | Excavation | Olliei | | |
| | Stairwell Drain | Yard- Front | | | | Other | | | |
| | Foundation Drain | Yard- Front Yard-Back | | | 16 | Outer | | | |
| | Building Interior | Yard- Side | | | | | | | |
| 09 | Danany menor | raru- Siue | Ī | | | 1 | Ī | | 1 |

| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page <u>3</u> of <u>3</u> | |
|---|---------------------------|---|
| Sewershed: JONES FALLS SEWERSHED | Company: Savin Engineers | Date: 7/30/08 |
| Test to be Performed: | Ground Condition: | Supervisor: RT |
| Smoke: _X Dyed Water: | Dry: X Damp: Wet: | |
| Manhole ID: S35EE 036 | Test ID: 0994-685 | Notifications Made: x (Residents, Fire, 311) |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



0994-685_OB01-01



0994-685_OB02-01